



# PP30 Air Lock Overhaul

---

**At 7000 run hours Maintenance is performed on the following items:**

- Replace: PP-HOP-CF\_A-CRG-ACME NUT
- Replace: PP-HOP-CF\_A-CRG-SLIDE BUSHING